

AIMS Console facilitates the following features

Various Filtering Capability

Grouping

Group by: Tower | Floor | Unit | Room | Aspect | Date snagged | Date fixed | Date de-snagged

Sort by: name | snag count | ascending | descending

Group dates by: day | week | month

Position: left | top

Then group by: None | Tower | Floor | Unit | Room | Aspect | Date snagged | Date fixed | Date de-snagged

Sort by: name | snag count | ascending | descending

Group dates by: day | week | month

Position: left | top

Then group by: None | Tower | Floor | Unit | Room | Aspect | Date snagged | Date fixed | Date de-snagged

Sort by: name | snag count | ascending | descending

Group dates by: day | week | month

Position: left | top

Display options

Display: bars | top ten snags | statistics

Show snags as: none | dots | thumbnail | tiny thumbnail | description

Filters

Snagging result: OK | not OK

Fixing result: fixed | can't fix | not a snag

De-snagging result: not rectified | partially rectified | rectified

Review status: reviewed | not reviewed

Tower/floor/unit: Tower A, Floor 2, 2341

Room: Bathroom, bedroom et

Item: Gap, crack etc.





















Aspect: electrical, plumbing, et

			Name ^	Description	Private	Include in visual report	Show to customer	Default
<input type="radio"/>	<input checked="" type="radio"/>	<input type="checkbox"/>	R_A_NOTOK	Executive Summary	<input type="checkbox"/> no	<input type="checkbox"/>	<input type="checkbox"/>	<input type="radio"/>
<input type="radio"/>	<input checked="" type="radio"/>	<input type="checkbox"/>	R_A_OK_NOTOK	Executive Summary	<input type="checkbox"/> no	<input type="checkbox"/>	<input type="checkbox"/>	<input type="radio"/>
<input type="radio"/>	<input checked="" type="radio"/>	<input type="checkbox"/>	TOP_TEN_SNAGS	Executive Summary	<input type="checkbox"/> no	<input type="checkbox"/>	<input type="checkbox"/>	<input type="radio"/>

Overall Project Inspection Status (During Execution and Finishing):

Tower A (8)	
Tower B (5)	
Tower C (2)	

Legend ^

- not yet snagged 
- OK 
- not OK, not yet fixed, not yet de-snagged 
- not OK, not yet fixed 
- not OK, fixed, not yet de-snagged 
- not OK, fixed, rectified 
- not OK, fixed, partially rectified 
- not OK, fixed, not rectified 
- not OK, fixed 
- not OK, can't fix, not yet de-snagged 
- not OK, can't fix, rectified 
- not OK, can't fix, partially rectified 
- not OK, fixed, not rectified 
- not OK, fixed 
- not OK, can't fix, not yet de-snagged 
- not OK, can't fix, rectified 
- not OK, can't fix, partially rectified 
- not OK, can't fix, not rectified 
- not OK, can't fix 
- not OK, not a snag, not yet de-snagged 


Overall status of inspection progress (grouped tower-wise)

Tower	Total	Completed	Remaining
Tower 2 (9,391)	8,895	4	
	Tower 2 Floor 1 (1,348)	1,294	54
	2013 (1,348)	1,294	54
	Tower 2 Floor 2 (1,536)	1,447	89
	2022 (1,536)	1,447	89
	Tower 2 Floor 25 (1,871)	1,788	83
	2251 (1,871)	1,788	83
	Tower 2 Floor 26 (1,424)	1,355	69
2263 (1,424)	1,355	69	
Tower 2 Floor 27 (1,348)	1,283	65	
2273 (1,348)	1,283	65	
Tower 2 Floor 28 (1,864)	1,728	136	
2281 (1,864)	1,728	136	
Tower 3 (4,485)	4,229	2	
	Tower 3 Floor 1 (1,541)	1,457	84
	3013 (1,541)	1,457	84
	Tower 3 Floor 27 (1,303)	1,224	79
	3273 (1,303)	1,224	79
Tower 3 Floor 29 (1,641)	1,548	93	
3291 (1,641)	1,548	93	

Overall status of Snags (grouped tower-wise)

Tower	Total	Completed	Remaining
Tower 2 (496)	496		
	Tower 2 Floor 1 (54)	54	
	2013 (54)	54	
	Tower 2 Floor 2 (89)	89	
	2022 (89)	89	
	Tower 2 Floor 25 (83)	83	
	2251 (83)	83	
	Tower 2 Floor 26 (69)	69	
2263 (69)	69		
Tower 2 Floor 27 (65)	65		
2273 (65)	65		
Tower 2 Floor 28 (136)	136		
2281 (136)	136		
Tower 3 (256)	256		
	Tower 3 Floor 1 (84)	84	
	3013 (84)	84	
	Tower 3 Floor 27 (79)	79	
	3273 (79)	79	
Tower 3 Floor 29 (93)	93		
3291 (93)	93		

Tower-wise, flat-wise and aspect-wise analysis of inspection findings



Statistics and Top Ten (most frequent) Snags

<p>Tower 3 (256)</p>	<p>256</p> <p>We found 256 snags.</p> <p>Top ten snags:</p> <ol style="list-style-type: none"> 1. Free of gaps between frame and wall? (35) 2. Is the flooring laid properly (without undulations)? (26) 3. Free from any cracks observed on the wall? (21) 4. "Are the gaps between flooring & skirting, filled with proper sealants?" (14) 5. No damage / Chipping in the dado observed? (12) 6. Are filling of the joints in corners of door frame done? (11) 7. Are the skirting tile joints properly filled? (10) 8. Are the holes in the door frame filled? (8) 9. No damage / chipping in the floor observed? (6) 10. Is the flooring material laid without shade variation? (6)
<p>Tower 4 (1,929)</p>	<p>95 618 321 895</p> <p>We found 1,929 snags.</p> <p>Top ten snags:</p> <ol style="list-style-type: none"> 1. Is the flooring laid properly (without undulations)? (186) 2. No damage / chipping in the floor observed? (108) 3. Free of gaps between frame and wall? (74) 4. "Are the gaps between flooring & skirting, filled with proper sealants?" (70) 5. Are flooring tile joints properly filled? (67) 6. Free from any cracks observed on the wall? (55) 7. Are the skirting tile joints properly filled? (48) 8. Are the skirting tiles free from undulations? (47) 9. No damage / Chipping in the dado observed? (38) 10. Is the Tower bolt functioning smoothly? (38)
<p>Tower 5 (2,475)</p>	<p>117 1,030 312 1,016</p> <p>We found 2,475 snags.</p> <p>Top ten snags:</p> <ol style="list-style-type: none"> 1. Is the flooring laid properly (without undulations)? (257) 2. No damage / chipping in the floor observed? (122) 3. Free of gaps between frame and wall? (105) 4. "Are the gaps between flooring & skirting, filled with proper sealants?" (87) 5. Are the skirting tiles free from undulations? (86) 6. Are the skirting tile joints properly filled? (81) 7. Are flooring tile joints properly filled? (60) 8. No damage / Chipping in the dado observed? (60) 9. Free from any cracks observed on the wall? (45) 10. Are filling of the joints in corners of door frame done? (42)

Thumbnail view of snags in dash board

Tower 5 (17)	5001 (17)	Bedroom 2 (7)	12%					24%					65%				
			12%					24%					65%				
		43%					57%										
		20%					10%					70%					
		Bedroom 2 Toilet (10)	20%					10%					70%				
			20%					10%					70%				

Tower 5 (23)	5223 (23)	Bedroom 2 (3)	57%					22%					22%									
			57%					22%					22%									
		100%																				
		60%					40%					22%					22%					
		Bedroom 2 Toilet (5)	60%					40%					22%					22%				
			60%					40%					22%					22%				
		Bedroom 3 (5)	40%					40%					20%									
			40%					40%					20%									
		Bedroom 3 Toilet (10)	50%					30%					20%									
			50%					30%					20%									